



Report Number	STC Number	Model	Report Title	Part Number	Date	Rev.
SIN-ECL-103	SH02-42 SR01632NY	AS 350 B3	SAFETY INFORMATION NOTICE - AIRFRAME MOUNTED FUEL FILTER	350-600024	14-Nov-11	0
SIN-AHCA-106	SH06-12 SR03771NY	AS 350, AS 355	REMINDER OF APPROVAL CONFIGURATION - EVRW		21-Sep-20	0
SB BO 105 LS 60-5		BO 105 LS A-3	REPLACEMENT OF HOSE		13-Mar-07	
SB BO 105 LS 60-6		BO 105 LS A-3	REMOVAL OF N2 OVERSPEED CONTROL SYSTEM		13-Mar-07	
SB BO 105 LS 60-7		BO 105 LS A-3	REPLACEMENT OF FUEL FILTER		31-Mar-05	
SB/ASB-10		BO 105 LS A-3	SB/ASB INDEX - CHAPTER 10		20-Sep-99	
SB/ASB-20		BO 105 LS A-3	SB/ASB INDEX - CHAPTER 20		20-Sep-99	
SB/ASB-30		BO105 LS	SB/ASB INDEX - CHAPTER 30		20-Sep-99	
SB/ASB-40		BO105 LS	SB/ASB INDEX - CHAPTER 40		20-Sep-99	
SB/ASB-50		BO105 LS	SB/ASB INDEX - CHAPTER 50		20-Sep-99	
SB/ASB-60		BO105 LS	SB/ASB INDEX - CHAPTER 60		20-Sep-99	
SB/ASB-70		BO105 LS	SB/ASB INDEX - CHAPTER 70		20-Sep-99	
SB/ASB-80		BO105 LS	SB/ASB INDEX - CHAPTER 80		20-Sep-99	



Report Number	STC Number	Model	Report Title	Part Number	Date	Rev.
SB/ASB-90		BO105 LS	SB/ASB INDEX - CHAPTER 90		20-Sep-99	
SB105LS-70-4		BO 105 LS A-3	(BO105 S.B. BINDER) STANDARD EQUT REPLACEMENT OF THE SAFETY HARNESS		17-Aug-00	
SB-BO 105 LS 30-10		BO 105 LS A-3	TAIL ROTOR - MODIFICATION OF THE TAIL ROTOR HEAD		19-May-05	
SB-BO 105 LS 40-10		BO 105 LS A-3	FLIGHT CONTROLS		11-May-09	
SB-BO 105 LS 80-32		BO 105 LS A-3	OPTIONAL EQUIPMENT, CARGO HOOK		06-May-09	
SB-BO 105 LS-80-11		BO105 LS	(BO105 S.B. BINDER) RETROFIT OF FUEL FLOW/AIR DATA COMPUTER DISPLAY		02-Jun-98	
SB-BO 105 LS-80-12		BO105 LS	(BO105 S. B. BINDER) OPT-ALLIED SIGNAL MST- 67A MODE S TRANSPONDER		08-Jun-98	
SB-BO 105 LS-80-13		BO105 LS	(BO105 BINDER) RETROFIT OF WIRE STRIKE PTROTECT. SYST., UPPER CUTTER		17-Jun-98	
SB-ECL-98- 76-002	SH96-32 SR00429NY	AS 350 B2, AS 350 BA	LEFT SIDE PILOT CONFIGURATION	350-400004	27-Jan-00	2
SB-ECL-99- 24-02	SH96-31 SR00422NY	AS 350, AS 355	BACKING PLATE AND STIFFNER RETROFIT ON BATTERY RELOCATION	350-790014	17-Aug-00	1
SB-ECL-99- 24-03		AS 350, AS 355	OPTIONAL RETROFIT OF CARGO POD LATCH COVERS	350-200834.80 350-200834.85	27-Jul-99	0
SB-ECL-99- 67-002	SH96-32	AS 350, AS 350 B2, AS 350 BA	COLLECTIVE LEVER LOCKING DEVICE	350-400144	29-Sep-99	2
SB-ECL-00- 52-001	SH00-1 SR1107NY	AS 350	HIGH VIS DOOR GUIDE ASSY INSTL.	350-202034 350-202044	15-Dec-00	1
SB-ECL-001A	SN 1002, 1022, 1033, 1028, 1055	EC 120 B	N.A.T. AUDIO SYSTEM POWER SOURCE,		11-Apr-00	0



Report Number	STC / SN Number	Model	Report Title	Part Number	Date	Rev.
SB-ECL-101	SN 3285	AS 350 B3	MODIFICATION OF HEATING INPUT	350-870034 350-870285 350-870334	28-Jan-02	0
SB-ECL-102	SN 3369, SN 3347 SN 3285	AS 350 B2, B3	ELT SYSTEM INSTALLATION CHECK	350-870904 350-870714 350-870404	11-Mar-02	0
SB-ECL-103	SH00-1 SR01107NY	AS 350	HIGH VISIBILITY DOORS	350-202014	31-May-02	0
SB-ECL-104	SH00-1 SR01107NY	AS 350	HIGH VISIBILITY DOORS	350-202034 350-202044	31-Jul-03	0
SB-ECL-105	SH94-29 SR00407NY	AS 350	LEFT-HAND LITTER KIT	350-200174	17-Jul-03	0
SB-ECL-106	SH96-62 SR00458NY	AS 350	RIGHT HAND LITTER KIT	350-200174	28-Jun-04	0
SB-ECL-107	SH02-39 SR01892NY	EC 120 B	IMPROVED HEATING SYSTEM	120-701014	30-Jun-04	0
SB-ECL-108	SH02-42 Issue 1-3 SR01632 dated Mar 18 2003 or earlier	EC 130 B4	AIRFRAME-MOUNTED FUEL FILTER	130-600004	18-Feb-05	4
SB-ECL-109	SH94-31 Issues 5-7 SR00379NY dated Mar 15 2004 or earlier	AS 350 B3	AIRFRAME-MOUNTED FUEL FILTER	350-600004	14-Jul-06	5
SB-ECL-110	O-LSH04-138	EC 130 B4	FM SYSTEM INTERLOCK DIODE	350-870084	07-Oct-04	0
SB-ECL-111		EC 120 B	FM SYSTEM INTERLOCK DIODE	350-870404	07-Oct-04	0



Report Number	STC / SN Number	Model	Report Title	Part Number	Date	Rev.
SB-ECL-112		AS 350 B2, B3	FM SYSTEM INTERLOCK DIODE	350-878564	07-Oct-04	0
SB-ECL-113	SH96-31 Issue 5 or earlier SR00422NY dated May 30 2002 or earlier	AS 350	BATTERY RELOCATION FUSE REPLACEMENT	350-700214 350-700324	19-May-05	1
SB-ECL-114	SN 3139 SN 3072/3072 SN 3142	AS 350 B3	AUDIO SYSTEM MODIFICATIONS	350-879354 350-879444 350-878854	11-Nov-04	0
SB-ECL-115	SN 2051 to 2054	BO 105 LS A-3	AUDIO LOW ROTOR WARNING	105-881594	14-Jan-05	0
SB-ECL-116	SH05-39	EC 130 B4	WIRE STRIKE PROTECTION SYSTEM	130-200214	13-Jan-06	0
SB-ECL-117	SN 1355	EC 120 B	SATELLITE PHONE	120-901704	22-Feb-07	0
SB-ECL-118	SH02-42 SR01632NY SH91-31 SR00379NY	AS 350 B3	AIRFRAME FUEL FILTER INSTALLTION	350-600024 350-600004	03-Apr-08	1
SB-ECL-119	SH02-42 SR01632NY	EC 130 B4	AIRFRAME FUEL FILTER INSTALLTION	130-600004	04-Jul-07	0
SB-ECL-120	SH04-28 Issue 2 or earlier	EC 130 B4	AFT BENCH SEAT ASSEMBLY	130-700614	20-Aug-12	1
SB-ECL-121	SH04-28 Issue 3 or earlier	EC 130 B4	AFT BENCH SEAT ASSEMBLY	130-700614	19-Feb-08	1
SB-ECL-122	SH96-32 Issue 7 or earlier SR00429NY dated Apr 29 1996 or earlier	AS 350 BA, B2, B3	LEFT HAND PILOT CONFIGURATION	350-400004 350-400074 350-400164	21-Sep-09	1

Service Bulletins, Service Information

Last Updated: 1 March 2022



Report Number	STC / SN Number	Model	Report Title	Part Number	Date	Rev.
SB-ECL-123	SN 3796	AS 350	COMM NAV SYSTEM MOD	ESK-1485 350-700614.10	26-Mar-09	0
SB-ECL-124	O-LSH98-107	AS 350 B3	SECURITY BARRIER INSTALLATION	350-702014	30-Jun-11	1
SB-ECL-125	SN 4423, 4566, 4702, 4885, 4945	EC 130 B4	DUAL BATTERY INSTALLATION	350 A62 2537 00	16-Nov-11	1
SB-ECL-126	SH96-126 Issue 4 or earlier	AS 350, AS 355, EC 130 B4	BLADE TIE DOWN WARNING FLAG	350-700414 130-700414	12-Sep-12	0
SB-AHCA-128	SH94-29 Issue 9 or earlier O-LSH93-0162 Issue 2 or earlier SR00407NY dated Aug 22 2005 or earlier	AS 350, AS 355	LITTER KIT	350-200034 350-200194	24-Mar-17	0
	SH96-62 Issue 5 or earlier O-LSH03-094/D Issue 1 O-LSH96-344/D Issue 2 or earlier SR00458NY dated June 16 2005 or earlier			350-200104		
SB-AHCA-129	SH96-61 SR00457NY SH14-40 SR03550NY	AS 350, AS 355, EC 130 T2	INSPECT FOR CORROSION ON CARGO MIRROR	350-200254 350-200264 130-201414	08-Nov-17	0



Report Number	STC / SN Number	Model	Report Title	Part Number	Date	Rev.
SB-AHCA-130	SH96-31 SR00422NY SR00800NY	AS 350, AS 355	BATTERY RELOCATION, INSPECT SCREW LENGTH	350-700324 355-700324	27-Aug-19	0
SB-AHCA-131	SH00-1 SR01107NY SH05-18 SR02141NY SH15-7	AS 350, AS 355	ALTERNATE DOOR LOCK FOR AHCA HIGH VISIBILITY DOORS	350-202014 350-202414 355-202014	25-Jul-19	0
SB-AHCA-133	SH17-47 SR04119NY	MBB-BK 117 C-2, D-2	INSTALLATION OF REMOVABLE DOOR PINS	135-201034 135-201014.11	11-Nov-21	1
SI-BO 105 LS-27		BO105 LS	SI-BO 105 LS-27		03-Dec-03	
SI-BO 105 LS-24		BO105 LS	SERVICE INFORMATION		28-Aug-01	
SI-BO 105 LS-29		BO 105 LS A-3	SERVICE INFORMATION		17-Feb-04	
SI-BO 105 LS-38		BO 105 LS A-3	LETTER FROM AIR CRUISERS		13-Mar-07	
SI-BO 105 LS-43		BO 105 LS A-3	SERVICE INFORMATION LETTER SIL-TIM-07-012 & -014		03-Apr-08	
SI-BO 105 LS-45		BO105 LS	INSTALL OF STCS W/ EUROCOPTER HOLDS NO RESPONSIBILITY		27-Aug-08	
SI-BO 105 LS-47		BO 105 LS A-3	NEW PART NUMBER DUE TO VENDOR DISCONTINUATION		14-Apr-09	
SI-BO 105-LS-20		BO 105 LS A-3	SX-16		24-May-06	



Report Number	STC / SN Number	Model	Report Title	Part Number	Date	Rev.
SI-BO-105-LS-21		BO105 LS	(BO 105 S.B. BINDER) Y2K INFORMATION		22-Nov-99	
SI-BO-105-LS-22		BO105 LS	(BO 105 S.B. BINDER) ALERT SERVICE INFORMATION		30-Mar-00	
SI-BO-105LS-25		BO105 LS	ALLIED SIGNAL INSTALLATION BULLETIN		07-May-02	
SI-ECL-97-00-02		AS 350	LEFT SIDE PILOT CONFIGURATION	SB-ECL-98-76-002	02-Jun-99	0
SI-ECL-99-00-01		AS 350	LEFT SIDE PILOT CONFIGURATION	SB-ECL-98-76-002	02-Jun-99	0
SI-ECL-00-25-001	SH97-60 SH91-36 SR00795NY SH7000SW-D	AS 355	COMPATIBILITY BETWEEN ECL CARGO PODS AND AEC SFIM	355-200814/24	15-Dec-00	0
SI-ECL-001	SH02-39 SR01892NY	EC 120 B	IMPROVED HEATING SYSTEM	FMS-ECL-102	21-Sep-05	1
SI-ECL-002	SH02-42 SR01632NY	AS 350 B3	AIRFRAME FUEL FILTER	350-600024	04-Aug-06	0
SI-ECL-003	SH02-42 SR01632NY	EC 130 B4	AIRFRAME FUEL FILTER	130-600004	04-Aug-06	0
SI-ECL-004	SN 3636, 3683, 3796, 3923	AS 350 B3	RYAN TCAD SYSTEM	350-871474 Rev B	21-Jun-06	0
SI-ECL-005	SN 1355	EC 120 B	RYAN TCAD SYSTEM	120-871294 Rev C	22-Jun-06	0
SI-ECL-006		AS 350 B2 w/VEMD, AS 350 B3, EC 120, EC 130	AURAL WARNING SIGNALS		28-Mar-08	0
SI-ECL-007	SH87-9	BO 105S CDN-BS	BLEED AIR HEATER	105S-810214	14-Apr-09	0

Service Bulletins, Service Information
Last Updated: 1 March 2022



Report Number	STC Number	Model	Report Title	Part Number	Date	Rev.
SI-ECL-008	SH96-32 O-LSH96-0314 O-LSH97-091 O-LSH08-288 SR00429NY SR00525NY	AS 350 BA, B2, B3	COLLECTIVE LOCK SYSTEM	FMS-ECL-9 MMS-ECL-36	19-Jun-09	0
SI-ECL-009	SH96-31 SR00422NY	AS 350, AS 355	BATTERY RELOCATION	350-700324.76	25-Jun-10	0
SI-ECL-010	SH96-31 SR00422NY SR00800NY	AS 350, AS 355	BATTERY RELOCATION	350-700324.77	25-Jun-10	0
SI-ECL-101	SH96-32 SR00429NY	AS 350	CARGO SWING INSTALLATION	350-400004, 350-400074, 350-400164	26-Feb-02	0
ASB40-8		BO105 LS	HYDRAULIC-FUNCTION TEST OF SOLENOID VALVE		15-Apr-96	0
ASB-BO 105 LS 30-8		BO105 LS	TAIL UNIT - INSP OF THE THICK OF THE SKIN PANELLING OF THE VERT. SKIN		29-May-03	0
ASB-BO 105 LS 10-11		BO 105 LS A-3	LIFTING SYSTEM - LIFE LIMITED PARTS		19-May-05	0
ASB-BO 105 LS 30-12		BO 105 LS A-3	TAIL ROTOR CHECK OF BALANCE WEIGHTS AND CONTROL LEVER		12-Dec-08	0
ASB-BO 105 LS 30-9		BO 105 LS A-3	CRACKS FOUND IN TAILBOOM BLIND RIVETS		19-Nov-04	0
ASB-BO 105 LS 80-28		BO 105 LS A-3	SPONTANEOUS REELING-OUT OF THE WINCH CABLE		22-Jun-04	0



Report Number	STC / SN Number	Model	Report Title	Part Number	Date	Rev.
ASB-BO 105 LS 80-29		BO 105 LS A-3	FIRE PROTECTION SYSTEM		11-Jun-07	0
ASB-BO 105 LS 80-31		BO 105 LS A-3	RESCUE HOIST		12-Jan-09	0
ASB-BO 105 LS-30-11		BO 105 LS A-3	TAIL ROTOR GEARBOX		28-May-08	0
ASB-BO 105 LS-80-30		BO 105 LS A-3	CARGO HOOK - CHECK KEEPER RETURN SPRING		24-Mar-08	0
ASB-BO105 LS-10-9		BO105 LS	ALERT SERVICE BULLETIN		17-Sep-97	0
ASB-BO105 LS-30-7		BO 105 LS A-3	TAIL ROTOR DRIVE		18-Jul-03	1
ASB- BO105LS-10- 10		BO 105 LS A-3	MAIN ROTOR SYSTEM		28-May-08	1
ASB-AHCA- 101	SH97-33, O-LSH97-063/D, O-LSH97-075/D O-LS97-107/D O-LSH97-135/D O-LSH97-150/D O-LSH97-152/D	AS 350, AS 355	REAR CARGO DOOR HINGE AND LATCH MODIFICATION	350-201064	07-Oct-20	0
	SH97-34	AS 350, AS 355	FORWARD-OPENING REAR CARGO DOOR	350-201014		
	SH97-34	EC 130	FORWARD-OPENING REAR CARGO DOOR	130-201004		